# Oil Field Environmental Incident Summary

Incident: 20151007093032 **Date/Time of Notice:** 10/07/2015 09:30 Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC. Well Name: STEELE 1-24H Field Name: BANKS Well File #: 19915 Date Incident: 10/6/2015 Time Incident: 11:45 Facility ID Number: **MCKENZIE** Twp: 152 **Rna**: 99 Sec: 24 Qtr: County: Location Description: Submitted By: NATE STANHOPE Received By: Contact Person: NATE STANHOPE PO BOX 268870 OKLAHOMA CITY, OK 73126 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - Within Dike Reported to NRC: No Units Spilled Recovered Units Followup **Units** Oil **Brine** 20 **Barrels** 20 Barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: N/A

Tuesday, January 31, 2017

Areal Extent:

N/A

## Potential Environmental Impacts:

Location soil

## Action Taken or Planned:

The well was shut-in, standing fluid was sucked up and impacted soil will be removed and replaced with clean fill.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

### **Updates**

Date: 10/7/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Release, due to a tank overflow, remained within dike and on the facility according to the report. NDIC retains oversight.